

Centric Display Installation

Part 1: Stand / Turntable

Step 1

Mount Stand & or Turntable base in desired location.

Step 2

Tilt Stand arms back at a 90 degree angle

Step 3

Place display on the Stand arms, align mounting holes on display with mounting holes on Stand arms.

Step 4

Attach display to Stand arms using the 4 supplied screws. Tighten in a crisscross pattern to 25inch pounds / 2.8 Newton meters.

Step 5

Insert screw covers over screws. Tap gently into place.

Step 2



Step 4



Step 5



Part 2: Connecting Cables to the Display

NOTE: Connect all video input cables before connecting the power

Step 1

Plug the DVI / VGA connectors into place and tighten screws firmly.

Step 2

Connect Composite and S-Video cables if applicable.

Step 3

Gently pull on all cables to ensure that they are connected securely.



Part 3: Connecting the Display to 115 / 230 VAC

Step 1

Ensure the voltage switch on the rear of display is on 115 VAC or 230 VAC as required.

Step 2

Connect power cable into the display and connect the male end into the proper power source.



Part 3: Connecting the Display to 24 VDC

Step 1

Using 14 gauge wire, connect both +/- ends to the DC power plug. Gently pull on wires to ensure they are connected securely.

Step 2

Connect opposite end to a regulated 24 VDC power source.

Step 3

Using a calibrated volt meter, ensure 24 VDC is being supplied to the DC power plug.

Step 4

Connect power plug to display, tighten fastening screws securely to the display.



For Technical Support contact support@nauticomp.com tel: 705-328-2992 fax: 705-328-2990