

Centric GB Display Installation Guide

Part 1: Flush Mount Display

Step 1

Refer to template for cutout dimensions.

Step 2


Slide display into cutout.

Step 3

Install bolt clips into slots on Centric GB Display.

Step 4

In a crisscross pattern tighten bolts to 25 in/lbs.



DO NOT OVER TIGHTEN (25 IN/LBS MAX)

Part 2: Connecting the Display to Power

Step 1

Plug male end of the 6ft ground power into appropriate outlet.

Step 2

Plug female end of the 6ft grounded power into the AC in on the rear of the display.

Step 3

Install the AC power clip and tighten the thumb screw. This is to ensure the AC power cable does not come loose.



Step 1

Step 2

Step 3

Part 3: Connecting Cables to the Display

PLEASE NOTE: ALWAYS CONNECT ALL VIDEO INPUT CABLES BEFORE CONNECTING THE POWER

Step 1

Press the VGA connector into place and tighten screws firmly, **DO NOT** over tighten

Step 2

Gently pull all cables to insure that they are connected securely.



For Any assistance with the operation of your new Centric GB Display, Please call us @ 705-328-2992

See reverse for Quick Reference Guide

NAUTICOMP